



INSPECCIÓN EVALUACIÓN — ADVANCED — ROCK PICKER JANUARY 2023

2019 Schulte 5000
Inventario: 259134
Serie: R80010120902
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Pattison Agriculture Limited / 731853
Humboldt, SK, S0K 2A0
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

								Costo estimado		
	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MAL	N/A	Observaciones	Repuestos	Mano de obra	Total
								0	0	0
MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO								0	0	0
INSPECTION/CONDITIONS								0	0	0

Stock Number: 259134

Model: 5000

Serial Number: R80010120902

							Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra Total
Customer:							WIMMER BROOK ENTERPRISES INC.		
Year: Make: Model:							2019 Schulte 5000		
Serial Number:							R80010120902		
Link to Picture Process:									

MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO

							Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra Total
1- Type							✓ Reel		
2- Drive							✓ Hydraulic		
3- Hopper Size							✓ 5 Yard		
4- Width of Pickup Forks							✓ 7'		
5- Tires: Brand and Size							Galaxy 22.5Lx16.1 14Ply Tires		
6- Misc.							✓ Hyd. Transport Swing		

INSPECTION/CONDITIONS

							Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra Total
1- Hydraulic Cylinders							✓ N/R leak on right bucket cylinder, may be coming from a fitting higher up on the cylinder, as it is leaking there and running down, not sure if that is the only leak on that cylinder		
2- Hoses							✓ Good		
3- Reel Drive Motor							✓ N/R coupling needs adjustment, important to note that this coupling a lot of the time seizes to the shaft not allowing the adjustment to happen, budget for a complete coupling as it often gets broke trying to adjust		
4- Teeth Shrouds							✓ Good chipped ice away from one tooth, it looks okay, teeth are replaceable teeth, could not see the rest froze in ice		
5- Reel Teeth / Length							✓ Good twine and fencing wire between reel and reel bearings, may need to replace a bearing if seal is gone		
6- Skip/ Body							✓ Good		
7- Bottom Bars							✓ Good		
Overall Summary of Unit							The left and right cam for grate lift is worn, this is a common issue with these units before they beefed up and installed a replaceable bushing, if customer complains directly to schulte's there is a good chance they will fix for free before trading as they were aware of this, otherwise some issues listed above, tires on unit in picture do not go with, the ones in the shed(picture) are the ones that go with. Unit overall is in fair condition for the year.		