



INSPECCIÓN EVALUACIÓN — ADVANCED — HUTSON FORAGE HARVESTERS
CHECKLIST

2023 John Deere 659
Inventario: 390084
Serie: 1KM0659GAPP143656
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Hutson, Inc. / 039156
St. Louis, MI, 48880
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

								Costo estimado		
	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MALE	N/A	Observaciones	Repuestos	Mano de obra	Total
TRADE INFO								0	0	0
FORAGE HARVESTER?								0	0	0
TYPE OF HEADER?		X						0	0	0
TIRES								0	0	0
CAB								0	0	0
ENGINE								0	0	0
DISPLAY AND ACTIVATIONS								0	0	0
CUTTERHEAD								0	0	0
OVERALL								0	0	0
PICTURES								0	0	0

Stock Number: 390084

Model: 659Serial Number: 1KM0659GAPP143656

TRADE INFO

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Purchased off HUT program in last 12 months? ☐ Si ☐ No										
What are they trading on?							TRADE WITH CHOPPER TOWARDS COMBINE AND HEAD			
Estimated Availability Date?							TODAY			
Estimated hours? ENGINE/CUTTER										
Idea how much they want?										
What do you think retail is?							\$45K			
Jockey / Wholesale bid?										
What do you recommend booking at?							\$35K			
Recommended repairs before resale with estimated price?										

FORAGE HARVESTER?

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Type										

TYPE OF HEADER?

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Type?							✓ Pick Up			
Model(s) of head(s)?										
Overall condition?		X								
Rows or Width?										
Rigid or Folding?										
Header Options?							✓ Gauge Wheels			
Paint & Sheet Metal		X								
Cutting devices and feed chains?										
Tines and strippers?										
Gear Boxes and slip clutches?										

TIRES

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
[tire_cond]										
Rear Axle?										
Are they damaged, cut or have lot of stubble wear?										

Stock Number: 390084

Model: 659 Serial Number: 1KM0659GAPP143656

CAB

							Costo estimado			
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
Owners Manual with Harvester? ☐ Si ☐ No										
Has it been smoked in? ☐ Si ☐ No Does it smell like mice? ☐ Si ☐ No										
Condition of seat?										
All lights work?										
Transmission?										
AC Work? ☐ Si ☐ No Heat & Defrost Work? ☐ Si ☐ No										
How is all the glass?										

ENGINE

							Costo estimado			
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
Any leaks on the engine? ☐ Si ☐ No Any leaks on the gear case? ☐ Si ☐ No										
13.5 Deere Engines also require two pictures in assessment: One of inside of coolant tank and One of Engine oil dipstick. Any oil in the coolant? ☐ Si ☐ No Any coolant in the oil? ☐ Si ☐ No										
Emissions Deleted or Modified? (WILL NOT TRADE FOR IF DELETED or MODIFIED) ☐ Si ☐ No										
Ext. Warranty with Expiration Date & Hours?										

DISPLAY AND ACTIVATIONS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Type of Display trading with harvester?										
Serial Number of Display?										
Type of Receiver trading with harvester?										
Serial Number of Receiver?										
Type of Activation's trading with harvester?										
Does it have HarvestLab 3000 or equivalent? ☐ Si ☐ No										

CUTTERHEAD

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Metal Detector? ☐ Si ☐ No										
Stone Detector? ☐ Si ☐ No										
Kernel Processor? ☐ Si ☐ No										
Condition of feed rolls										
Condition of Knives and Stationary Knife?										
Condition of Blower Fan										

OVERALL

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Condition of Belts and Chains?										
Paint Appearance?										
Is there any damage? If so, please describe & include picture ☐ Si ☐ No										
Is there any damage? If so, please describe & include picture ☐ Si ☐ No										
List other options?										

PICTURES

							Costo estimado			
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
Remember to take photos: 1) Full of each side (Right and Left) 2) Full Front, Right corner & Left corner 3) Full Rear, Right corner and Left corner 4) Cab a. Seat b. Headliner c. Control panel d. Hour meter e. W/display all activations 5) Feed Rolls, Knives, Blower Housing and Paddles 6) All tires, one close-up and one of whole tire 7) Serial number plate 8) Discharge Shoot 9) Heads 10) Take photo of any damage 11) 13.5 Deere Engines also require two pictures in assessment: One of inside of coolant tank and One of Engine oil dipstick.										